depending upon the nature and quantity of the combustible material exposed.

2.2.3 Fire watch.

2.2.3.1 Fire watches shall be required whenever welding or cutting is performed in locations where anything other than a minor fire might develop, or any of the following conditions exist:

2.2.3.1.1 Appreciable combustible material, in building construction or contents, closer than 35 feet (10.7 m) to the point of operation.

2.2.3.1.2 Appreciable combustibles are more than 35 feet (10.7 m) away but are easily ignited by sparks.

2.2.3.1.3 Wall or floor openings within a 35 foot (10.7 m) radius expose combustible material in adjacent areas including concealed spaces in walls or floors.

2.2.3.1.4 Combustible materials are adjacent to the opposite side of metal partitions, walls, ceilings, or roofs and are likely to be ignited by conduction or radiation.

2.2.3.2 Fire watchers shall have fire extinguishing equipment readily available and be trained in its use. They shall be familiar with facilities for sounding an alarm in the event of a fire. They shall watch for fires in all exposed areas, try to extinguish them only when obviously within the capacity of the equipment available, or otherwise sound the alarm. A fire watch shall be maintained for at least a half hour after completion of welding or cutting operations to detect and extinguish possible smoldering fires.

2.2.4 Authorization. Before cutting or welding is permitted, the area shall be inspected by the individual responsible for authorizing cutting and welding operations. He/she shall designate precautions to be followed in granting authorization to proceed, preferably in the form of a written permit.

2.2.5 Floors. Where combustible materials such as paper clippings, wood shavings, or textile fibers are on the floor, the floor shall be swept clean for a radius of 35 feet (10.7 m). Combustible floors shall be kept wet, covered with damp sand, or protected by fire-resistant shields. Where floors have been wet down, personnel operating arc welding or cutting equipment shall be protected from possible electrical shock.

2.2.13 Management. Management shall recognize its responsibility for the safe usage of cutting and welding equipment on its property and:

2.2.13.1

2.2.14.6 Sginadall determine that fire protection and extinguishing equipment are properly located at the site.

2.2.14.7 Were fire watches are required, de/she shall see tdat they are available at the site.

shall be removed from the holders and the holders carefully located so that accidental contact cannot occur and the machine disconnected from the power source.

3.4.6 Gas cylinder shutoff. In order to eliminate the possibility of gas escaping through leaks of improperly closed valves, when gas welding or cutting, the torch valves shall be closed and the fuel-gas and oxygen supply to the torch positively shut off at some point outside the confined area whenever the torch is not to be used for a substantial period of time, such as during lunch hour or overnight. Where practicable the torch and hose shall also be removed from the confined space.

3.4.7 Warning signs. After welding operations are completed, the welder shall mark the hot metal or provide some other means of warning other workers.

4. Health protection and ventilation.

4.1 General

4.1.1 Contamination. The requirements for contamination control have been established on the basis thqurning 19.35 9.35 T-(r mq0.0000092a5l6(u)-33(rnin)[ )]

tion

4.1.4 Precautionary labels. A number of potentially hazardous materials are employed in fluxes, coatings, coverings, and filler metals used in welding and cutting or are released to the atmosphere during welding and

4.4.4 Outside helper. Where University welding operations are carried on in confined spaces and where welders and helpers are provided with hose masks, hose masks with blowers, or self-contained breathing equipment approved by the Mine Safety and Health Administration and the National Institute for Occupational Safety and Health, a worker shall be stationed on the outside of such confined spaces to insure the safety of those working within. This will be done in accordance with the University confined space standard practice instructions.

4.4.5 Oxygen for ventilation. Because of itsôflammable properties, Oxygen shall never be used for ventilation.

4.5 Fluorine compounds.

4.5.1 General. In confined spaces, welding or cutting involving fluxes, coverings, or other materials which contain fluorine compounds shall be done in accordance with the safety precautions and work practices delineated on the MSDS. A fluorine compound is one that contains fluorine, as an element in chemical combination, not as a free gas.

4.5.2 Maximum allowable concentration. The need for local exhaust ventilation or airline respirators for welding or cutting in other than confined spaces will depend upon the individual circumstances. However, experience has shown such protection to be desirable for fixed-location production welding and for all production welding on stainless steels. Where air samples taken at the welding location indicate that the fluorides liberated are below the maximum allowable concentration, such protection is not necessary.

4.6 Zinc.

4.6.1 Confined spaces. In confined spaces welding or cutting involving zinc-bearing base or filler metals or metals coated with zinc-bearing materials shall be done in accordance with the "Ventilation in confined space" section of this SPI.

4.6.2 Indoors. Indoors, welding or cutting involving zinc-bearing base or filler metals coated with zinc-bearing materials shall be done in accordance with the "Local exhaust hoods and booths" section of this SPI.

4.7 Lead.

or other pressure restraining devices. Also, protection shall be provided against expulsion of loose dirt that may have become trapped in the pipe.

5.1.5 Construction standards. The welded construction of transmission pipelines shall be conducted in accordance with the Standard for

- Have all flammable items in the hot work area been removed or covered?

Action

Action Taken: **YES (___) NO (___)**

9. Definitions.

Welder and welding operator mean, any operator of electric or gas welding and cutting equipment.

Approved means, listed or approved by a nationally recognized testing laboratory. Refer to 29 CFR 1910.155 for definitions of listed and approved, and 29 CFR 1910.7 for nationally recognized testing laboratory.

All other welding terms are used in accordance with American Welding Society.